



*The torsion housing supports the outer rear pan, so I pre-drilled some holes through the floor, then welded them up. This will ensure a good weld penetration through the material.*



*With the welding finished it's time to seal the pieces. I used a silicone-based sealer and ran an even bead around the section on top and underneath.*



*A picture says it all. There's nothing like a new floor section.*